

A photograph of a metal exhaust pipe assembly, likely from a vehicle. The pipe is made of metal and shows signs of wear, including rust and discoloration. It features a central cylindrical component, which is a catalytic converter, mounted on a flange. The pipe has a curved section and ends in a flange on the left and a flange on the right. The background is a plain, light-colored surface.



MARMITTA CENTRALE
SUZUKI JIMNY «II» (2018)
1.5 AllGrip , 16v. Fuoristrada, 3 p. (4WD) dal 2018-07 al » cm3 1462 cv 102 valv. 16 (B)
78RM02

ACQUISTALO SUL NOSTRO SITO AUTODEMOLIZIONERIMINI COM INSERENDO NELLA RICERCA
IN ALTO LA MATRICOLA: it041800

RICAMBI NUOVI E USATI A CASA TUA IN 24 - 48 H

BONIFICO BANCARIO - BANCOMAT E CARTA DI CREDITO PER RITIRO A MANO

WHATSAPP 331 4444410

TELEFONO 0541 380475

CODICE PRODUTTORE: 1426078R00000

CODICE ALTERNATIVO: 78R-M02

~~CODICE MOTORE VEICOLO: K15B~~

 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z	 MARMITTA CENTRALE SUZUKI JIMNY laquoiraquo (2018) https://www.annunci.it/x-659992-z
--	--	--	--	--	---	--	--	--	---

CONTATTACI TELEFONICAMENTE OPPURE MAIL SMS WHATSAPP 0541 380475 331 4444410

DISPONIBILI NUMEROSI RICAMBI, ANCHE SE NON ELENCATI, INVIACI LA TUA RICHIESTA
TRAMITE MAIL - WHATSAPP, OPPURE VISITA IL NOSTRO SITO AUTODEMOLIZIONERIMINI

Tel: 3314444410